



X2		MC6205
1A	→	1A
1B	→	1B
2A	→	2A Выб 0
2B	→	2B Выб 1
3A	→	3A +12В
3B	→	3B +12В
4A	→	4A +12В
4B	→	4B +12В
5A	→	5A
5B	→	5B
6A	→	6A C2 стр.
6B	→	6B C1 стр.
7A	→	7A +12В
7B	→	7B A2
8A	→	8A Маркер
8B	→	8B A1
9A	→	9A
9B	→	9B
10A	→	10A Сброс Ст.
10B	→	10B A3
11A	→	11A Общи
11B	→	11B A6
12A	→	12A Сброс стб.
12B	→	12B A5
13A	→	13A
13B	→	13B
14A	→	14A A4
14B	→	14B A7
15A	→	15A Общи
15B	→	15B C1 ст.
16A	→	16A Загр. Адр
16B	→	16B Зап.И
17A	→	17A
17B	→	17B
18A	→	18A 0 сброс
18B	→	18B ИБ
19A	→	19A Общи
19B	→	19B Готов
20A	→	20A A8
20B	→	20B И3
21A	→	21A
21B	→	21B
22A	→	22A И1
22B	→	22B И2
23A	→	23A Общи
23B	→	23B И5
24A	→	24A И4
24B	→	24B И7
25A	→	25A
25B	→	25B
26A	→	26A +5В
26B	→	26B +5В
27A	→	27A Общи
27B	→	27B +5В
28A	→	28A +5В
28B	→	28B +5В
29A	→	29A
29B	→	29B
30A	→	30A Прогон
30B	→	30B Общи 12В
31A	→	31A Общи 12В
31B	→	31B Общи 12В
32A	→	32A Общи 12В
32B	→	32B Общи 12В